



Eastern spring: Before 2022 works





Eastern spring: After April 2022 works





Direction of flow

Adjustable spillway set to 3m AHD

Levee bank

Backfilled drains

Insufficient spoil to backfill / drain not functional

Groundwater near surface level under tea-tree

Eastern springs: April 2022 works summary